

☐ Click to enlarge

MCB Bridgeport
Station: 1
Shifts Or Platoon: A

Location: 207 Vitorri CT Coleville DD 96107	Incident Type: 100 - Fire, other
Zone: 10 - Coleville Family Housing Location Type: 1 - Street address	FDID: M2205 Incident #: 2012-30 Exposure ID: 4035772 Exposure #: 0 Incident Date: 02/03/2012 Dispatch Run #: 2012-030

Report Completed by: Sullivan , Kevin M	ID: 5200	Date: 02/29/2012
Report Reviewed by: Sullivan , Kevin M	ID: 5200	Date: 02/29/2012
Report Printed by: Sullivan, Kevin M	ID: 5200	Date: 2/29/2012 Time: 19:36

Structure Type:	Property Use: 419 - 1 or 2 family dwelling	
Automatic Extinguishment System Present: <input type="checkbox"/>	Detectors Present: <input type="checkbox"/>	Cause of Ignition:
Aid Given or Received: Automatic aid given	Primary action taken: 11 - Extinguishment by fire service personnel	
Mutual AID	Their FDID: 26015	Their State: CA
		Their Incident #: 0203039
Additional actions: 21 - Search , 24 - Recover body		
Losses	Pre-Incident Values	
Property:	Property:	Civilian Injuries: 0
Contents:	Contents:	Fire Service Injuries: 0
Total:	Total:	Civilian Fatalities: 1
		Fire Service Fatalities: 0
		Total Casualties: 1
		Total Fire Service Casualties: 0
Total # of apparatus on call:		3
Total # of personnel on call:		11

NARRATIVE

Narrative by Lieutenant Michael Lightfoot ---

MWFES monitored a dispatch by Mono County for AVFD to respond to a structure fire in base housing. Immediately following the monitored dispatch, the housing gate patrol radioed Control advising of a series of explosions and a house on fire at base housing, and requesting base fire to respond. Control toned us out and we responded with myself in the Squad, a crew of 3 in the engine and 2 in the ambulance. En route to the scene radio traffic was monitored from AVFD advising of a working incident, with several seriously injured victims and CPR in progress. --

Upon arrival at the scene, we found a duplex style housing unit, with the left half of the structure severely damaged by an apparent explosion and the debris pile well involved in fire. All structures immediately adjacent to the "ground zero" structure also had sustained heavy damage. Many walking wounded were observed in the area with a joint law enforcement element establishing crowd control. AVFD was already on scene with an engine and a utility. A defensive attack was in progress with two 2 1/2 inch lines and a fixed monitor. Mono, Medic 1 was treating a female with extensive burns and 1 deceased victim was located in front of the right side dwelling of the duplex. MWFES engine 30 was assigned as back up and establishing a secondary water supply. Ambulance 71 was directed to a nearby residence to treat a male burn victim. MWFES chief 5200 arrived on scene and AVFD transferred command to him with AVFD chief assuming operations. Mutual aid was requested from East Fork Fire and additional care flight air ambulances were requested to the scene. --

At this time I was re-assigned to a command liaison position at the EOC being established at

ENCLOSURE (A)

EN(8)

the housing community center. I reported to the EOC at this time and re-assigned MWFES ambulance 71 to community center medical group due to the influx of walking wounded into the center. The EOC was immediately staffed with the Anti Terrorism Officer, MCPD, MWTC Command staff, and myself as the FD rep. In the EOC, coordination was made to track patients destination and status, provide for residents to re-enter their homes to retrieve belongings and arrange support for the fire fighting, rescue and USAR operations. -- After the transition from attack and stabilization of the incident to patrol status, I was re-assigned to the overhaul group. All resources except MWFES personnel had been released from the scene, and we escorted residents into the area immediately surrounding ground zero, to collect personal effects. We also assisted maintenance personnel from Lincoln Military Housing in securing water to the affected units. Several hot spots were found and extensive overhaul was taken to eliminate the smoldering material. Ambulance 71 was requested to return to the community center for an additional male patient complaining of back pain. The crew assessed the patient and decided to transport the male code 2 to Carson Valley Medical Center for treatment of blunt force trauma from a stationary object. This patient was in the housing unit immediately adjacent to the blast zone and was thrown approximately 20 feet into an interior wall of his house. A final walk around of the scene was performed and the fire was declared dead-cold out. Chief 5200 remained on scene for the remainder of the nite along with Captain 5210. MCPD provided scene security and patrols of the immediate area to preserve evidence pending the completion of a formal investigation. The EOC was manned throughout the nite by MCPD and MWTC Command staff. -- Engine 30 returned to the installation without further incident and ambulance 71 returned following their transfer of patient care at CVMC. -Report submitted by Lt. Lightfoot as an addition to the narrative being provided by the incident commander, Chief Sullivan. -MLL-

On the evening of February 3, 2012 while off duty at my place of residence in Wellington, Nevada at approximately 2045hrs. I was sitting in my living room when a large noise that sounded like a vehicle driving through a wall was heard. Looked over at my wife who was aside me on the sofa to ask, "Did you just hear that?" Her reply was "Yes." I explained that I would go check out around the house, when my home phone rang. After my wife answering the home phone, she immediately handed the phone to me only to be told by the Marine Corps Police Dispatch Center that we have had an explosion in Coleville Housing. I advised the dispatcher to immediately start a mandatory recall of off duty firefighters and that I was enroute to Coleville Housing. This all occurred between 2045 hrs - 2110 hr. At approximately 2112, I departed the house enroute to Coleville housing area. I was on the road within 2 minutes of the time being notified of the issue. I contacted Captain Keith Preston and informed him to start a mandatory off duty firefighter recall, just in case the notification process was delayed. He informed me that he was notified as well, and was enroute to the location. As was I driving toward the Coleville housing area, you could see large amounts of glowing lights and smoke from that area. Once arrived on scene, at 2123hrs. Upon arrival, my first scene size-up was that we had a lot of blowing debris across the entire Lincoln Military Housing area in Coleville. Flying debris of insulation was scattered throughout the installation. As I headed toward the incident site, there was housing debris scattered all over the roadway and adjacent lawns to the affected house. Once at the scene of the incident, I noticed that Antelope Valley Fire Department (AVFD) and Mono County Paramedic Unit Medic 1 were on scene. AVFD was performing firefighting efforts on the structure that was on fire, while Medic 1 was tending to patients that were being pulled out of the burning/damaged structures. Marine Corps Marines were surrounding a patient on the ground that had been declared deceased at the scene, due to injuries caused by the incident and covered by a yellow tarp. I made contact with the on scene officer in charge from Antelope Valley Fire Department, Assistant Chief (AC) Jason Foster who was in charge of the incident. I advised

him that I would be assuming Incident Command of the emergency and he would remain in charge of Operations as the Operations Officer. At which time, AC Foster provided me a summary of what has taken place, allowing me to be able to paint a picture of the events that had already taken place, a current status and any other actions needed. Mountain Warfare Fire & Emergency Services (MWFES) arrived on scene at approximately the same time as I did, which they were placed in the Operational control of AC Foster for firefighting operations and assisting with the medical needs of the patients. During which time, the incident was named Lincoln Command. Was contact by phone and advised by AVFD Fire Chief Mike Curti, that Cal-Fire Investigators from the State Fire Marshall's Office was notified. Requested East Fork Fire & Paramedic District Fire Investigator Terry Taylor, but later was advised he was not available. As the Incident Commander, I requested the propane main line be shut down to prevent further potential exposures or structural fires. Requested Red Cross representative for the assist to the families affected from the explosion disaster. Requested through Mono County Dispatch for additional resources from surrounding agencies; East Fork Fire & Paramedic District was notified and responded to the incident. Managed the incident to ensure firefighter safety, property preservation, exposure protection, extinguishment and patient care was handled. East Fork Fire Department Engine 4 and Rescue 4 arrived on scene with Battalion Chief / Training Captain for assistance. At which time, they were placed in as the Safety Officer on scene and provided assistance to the Operational firefighting crews. Care Flight had been notified by Mono County Dispatch in regards to the number of patients needing Advanced Life Support services due to the extent of their injuries. A total of three Care Flight Air EMS assets were requested and landed in the ball fields of the Lincoln Military Housing area, where the two critically burned / injured patients were transported by wheeled ambulance (ALS unit from Mono County Paramedics) to the Landing Zone for the Care Flight helicopters. Two Care Flight units departed with the critically burned leaving one Care Flight helicopter on ground standby. Patients were then loaded and transported to nearby trauma/ burn facilities in Reno or Sacramento. Utilities were secured. Evacuation was accomplished. A second search of the incident site, determined no further patients at which time overhaul operations were conducted to prevent rekindle. The Emergency Operations Center (EOC) was stood up at the Community Center where the Command conducted coordination and control of the overall incident activities. During this time, it was asked to send a medical officer to the Community Center to provide patient assessment of those affected directly by the explosion blast and the efforts associated with rescuing the victims from the incident location. At which time, I sent MWFES medical crew and Acting Fire Captain, Lieutenant Michael Lightfoot down to the Community Center auditorium to set up a medical triage location for personnel needing direct medical assessment or treatment. While the medical crew was in the Community Center auditorium providing medical patient assessments of those residents who might have been affected by the smoke inhalation, flying insulation debris or other related walk-in emergencies. MWFES medical crew transported one patient with possible back injuries associated with the blast of the explosion since his home was adjacent to the emergency. The incident was terminated and all resources were released at 0107 hours. MWFES remained on scene throughout the evening to ensure no flare ups occurred at the incident location and to assist the Marine Corps Police Department for scene preservation and security reasons. On Saturday morning, MWFES was tasked by the EOC to provide an initial assessment of the surrounding structures to determine habitability conditions. During this time frame, we had several families displaced due to the extent of damages to their homes, utilities and propane being shutdown during the emergency. A validation of the propane system was accomplished with the accompanying Lincoln Housing Maintenance staff and local propane company staff allowing the propane system to be turned back on to the homes not directly affected. Leak checks and safety conditions were conducted with agency crews. I remained on scene during the recovery phase of the emergency allowing the sense of reassurance to the families affected during the incident. Providing propane service checks for leaks and odors associated with concerned family members using a five gas detector. Each and every home was inspected on

numerous occasions to ensure life safety issues were not present. Allowing nonaffected housing occupants to return to their homes. Provided facility inspections and guidance to the families regarding the use of propane and the associated smells with using propane for their home appliances; creating a sense of understanding by the families and allowing a sense of assurance that their homes were safe to live in.

Estimated cost of damage of Lincoln Military Housing assets has not been provided at this time. Total value of personal belongings to the families affected by the explosion has not been provided at this time. Cause of explosion has not been determined at this time. Investigation is handled by NCIS Special Agency Kelly Rigsby. Lincoln Management Authority representative was Carolyn Parker. BiState/ AmeriGas Propane Company representative was Joel out of the Gardnerville, Nevada office. THIS INFORMATION IS TO THE BEST OF MY KNOWLEDGE OF WHAT HAPPENED AT THE EMERGENCY LOCATED IN COLEVILLE HOUSING. NO FURTHER INFORMATION.KMS

APPARATUS

Unit	5220	Unit	5230
Type:	Support apparatus, other	Type:	Engine
Use:	Other	Use:	Suppression
Response Mode:	Lights and Sirens	Response Mode:	Lights and Sirens
# of People	1	# of People	3
Injury Or Onset	02 /03/2012 20:53:00	Injury Or Onset	02 /03/2012 20:53:00
Alarm	02 /03/2012 20:53:00	Alarm	02 /03/2012 20:53:00
Dispatched	02 /03/2012 20:56:00	Dispatched	02 /03/2012 20:56:00
Enroute	02 /03/2012 20:56:00	Enroute	02 /03/2012 20:56:00
Arrived	02 /03/2012 21:23:00	Arrived	02 /03/2012 21:45:00
Cancelled	-- /-- /-- --:--:--	Cancelled	-- /-- /-- --:--:--
Cleared Scene	02 /04/2012 02:30:00	Cleared Scene	02 /04/2012 02:30:00
In Quarters	02 /04/2012 03:00:00	In Quarters	02 /04/2012 03:00:00
In Service	02 /04/2012 03:00:00	In Service	02 /04/2012 03:00:00
Unit	5271		
Type:	BLS unit		
Use:	EMS		
Response Mode:	Lights and Sirens		
# of People	2		
Injury Or Onset	02 /03/2012 20:53:00		
Alarm	02 /03/2012 20:53:00		
Dispatched	02 /03/2012 20:56:00		
Enroute	02 /03/2012 20:56:00		
Arrived	02 /03/2012 21:45:00		
Cancelled	-- /-- /-- --:--:--		
Cleared Scene	02 /04/2012 02:30:00		
In Quarters	02 /04/2012 03:00:00		
In Service	02 /04/2012 03:00:00		
Number Of People not on apparatus: 5			

CIVILIAN CASUALTIES 1

Gender	Name	Age	Date Of Birth	Race	Ethnicity	Hispanic
Female	(b) (6)					
Affiliation	Date Of Injury			Time Of Injury		

Civilian	02 /03/2012	20 :50:
Severity	Cause Of Injury	
Death	Undetermined	
Human Factors	None	
Contributing		
Contributing Factors 1	Contributing Factors 2	Contributing Factors 3
Wall collapse		
Activity When Injured	Location At Time Of Incident	General Location At Time Of Injury
Undetermined	Not in area of origin, but involved in starting the fire	In building of origin, but not in area of origin
Story At Start Of Injury	Story Where In jury Occured	Specific Location At Time Of Injury
1	1	Unknown
Primary Apparent Symptom	Primary Part Of Body Injured	Disposition
Crushing	Multiple body parts	
Remarks		
Upon arrival of MWFES, the victim had already been pronounced deceased by Mono County Paramedics. The victim had ben removed from the structure and CPR had been administered by bystanders until the arrival of EMS.		

PATIENT #1 - PCR 1080829

Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
		(b) (6)	
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)

PATIENT HISTORY

Primary Symptom:	What happened to this patient:	Condition Code Number:
Breathing Problem	Treated and Released	(8010) [Difficulty Breathing (ALS-786.05)]

PATIENT NARRATIVE:

Pt was having problem breathing. Givin O2 @15l NRB
Review Requested: No

COMPLAINT

Chief Complaint Narrative	Throat Irritation
Complaint Anatomic Location	Neck
Primary Symptom	Breathing Problem
Providers Primary Impression	Respiratory distress

DESTINATION

Incident Patient Disposition	Treated and Released
------------------------------	----------------------

EMS PERSONNEL	ID	ROLE
(b) (6)	0325	Other

(b) (6)		0360	Primary Patient Caregiver
PATIENT #2 - PCR 1080835			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
(b) (6)	(b) (6)	(b) (6)	(b) (6)
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)

PATIENT HISTORY		
Primary Symptom:	What happened to this patient:	Condition Code Number:
Breathing Problem	Treated and Released	(8010) [Difficulty Breathing (ALS-786.05)]

PATIENT NARRATIVE:
Pt was having problem breathing. Givin O2 @15l NRB
Review Requested: No

COMPLAINT	
Chief Complaint Narrative	Upper Respiratory
Complaint Anatomic Location	Chest
Primary Symptom	Breathing Problem
Providers Primary Impression	Respiratory distress

DESTINATION	
Incident Patient Disposition	Treated and Released

EMS PERSONNEL	ID	ROLE
(b) (6)	0325	Other
(b) (6)	0360	Primary Patient Caregiver

PATIENT #3 - PCR 1080843			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
(b) (6)	(b) (6)	(b) (6)	(b) (6)
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)

PATIENT HISTORY		
Primary Symptom:	What happened to this patient:	Condition Code Number:
Breathing Problem	Treated and Released	(8010) [Difficulty Breathing (ALS-786.05)]

PATIENT NARRATIVE:
Pt was having problem breathing. Givin O2 @15l NRB
Review Requested: No

PATIENT HISTORY			
Primary Symptom: Breathing Problem	What happened to this patient: Treated and Released	Condition Code Number: (8010) [Difficulty Breathing (ALS-786.05)]	
PATIENT NARRATIVE:			
Pt was having problem breathing. Givin O2 @15l NRB Foot was flushed and bandaged. Review Requested: No			
COMPLAINT			
Chief Complaint Narrative	Breathing Difficulty and Puncture in foot from nail		
Complaint Anatomic Location	Chest		
Primary Symptom	Breathing Problem		
Providers Primary Impression	Respiratory distress		
DESTINATION			
Incident Patient Disposition		Treated and Released	
EMS PERSONNEL	ID	ROLE	
(b) (6)	0325	Primary Patient Caregiver	
	0360	Secondary Patient Caregiver	
PATIENT #6 - PCR 1080849			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
(b) (6)	(b) (6)	(b) (6)	(b) (6)
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)
PATIENT HISTORY			
Primary Symptom: Breathing Problem	What happened to this patient: Treated and Released	Condition Code Number: (8010) [Difficulty Breathing (ALS-786.05)]	
PATIENT NARRATIVE:			
Pt was having problem breathing. Givin O2 @15l NRB. Review Requested: No			
COMPLAINT			
Chief Complaint Narrative	Breathing Difficulty		
Complaint Anatomic Location	Chest		
Primary Symptom	Breathing Problem		
Providers Primary Impression	Respiratory distress		
DESTINATION			
Incident Patient Disposition		Treated and Released	
EMS PERSONNEL	ID	ROLE	

(b) (6)		0325 0360	Other Primary Patient Caregiver
PATIENT #7 - PCR 1080853			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
		(b) (6)	
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)
PATIENT HISTORY			
Primary Symptom:	What happened to this patient:	Condition Code Number:	
Breathing Problem	Treated and Released	(8010) [Difficulty Breathing (ALS-786.05)]	
PATIENT NARRATIVE:			
Pt was having problem breathing. Givin O2 @15l NRB.			
Review Requested: No			
COMPLAINT			
Chief Complaint Narrative	Breathing Difficulty		
Complaint Anatomic Location	Chest		
Primary Symptom	Breathing Problem		
Providers Primary Impression	Respiratory distress		
DESTINATION			
Incident Patient Disposition		Treated and Released	
EMS PERSONNEL	ID	ROLE	
(b) (6)	0325	Other	
	0360	Primary Patient Caregiver	
PATIENT #8 - PCR 1080857			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
		(b) (6)	
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)
PATIENT HISTORY			
Primary Symptom:	What happened to this patient:	Condition Code Number:	
Breathing Problem	Treated and Released	(8010) [Difficulty Breathing (ALS-786.05)]	
PATIENT NARRATIVE:			

Pt was having problem breathing. Givin O2 @15l NRB.

Review Requested: No

COMPLAINT

Chief Complaint Narrative	Breathing Difficulty
Complaint Anatomic Location	Neck
Primary Symptom	Breathing Problem
Providers Primary Impression	Respiratory distress

DESTINATION

Incident Patient Disposition Treated and Released

EMS PERSONNEL

ID

ROLE

(b) (6)

0325

Other

0360

Primary Patient Caregiver

PATIENT #9 - PCR 1080863

Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
(b) (6)	(b) (6)	(b) (6)	(b) (6)

Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)

PATIENT HISTORY

Primary Symptom:	What happened to this patient:	Condition Code Number:
Breathing Problem	Treated and Released	(8010) [Difficulty Breathing (ALS-786.05)]

PATIENT NARRATIVE:

Pt was having problem breathing. Givin O2 @15l NRB.

Review Requested: No

COMPLAINT

Chief Complaint Narrative	Breathing Difficulaty
Complaint Anatomic Location	Chest
Primary Symptom	Breathing Problem
Providers Primary Impression	Respiratory distress

DESTINATION

Incident Patient Disposition Treated and Released

EMS PERSONNEL

ID

ROLE

(b) (6)

0325

Other

0360

Primary Patient Caregiver

PATIENT #10 - PCR 1080866

Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
(b) (6)	(b) (6)	(b) (6)	(b) (6)

(b) (6)			
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)

PATIENT HISTORY		
Primary Symptom:	What happened to this patient:	Condition Code Number:
Breathing Problem	Treated and Released	(8010) [Difficulty Breathing (ALS-786.05)]

PATIENT NARRATIVE:	
Pt was having problem breathing. Givin O2 @15l NRB.	
Review Requested: No	

COMPLAINT	
Chief Complaint Narrative	Breathing Difficulty
Complaint Anatomic Location	Chest
Primary Symptom	Breathing Problem
Providers Primary Impression	Respiratory distress

DESTINATION	
Incident Patient Disposition	Treated and Released

EMS PERSONNEL	ID	ROLE
(b) (6)	0325	Other
(b) (6)	0360	Primary Patient Caregiver

PATIENT #11 - PCR 1080871			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
(b) (6)	(b) (6)	(b) (6)	(b) (6)

Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)

PATIENT HISTORY		
Primary Symptom:	What happened to this patient:	Condition Code Number:
Breathing Problem	Treated and Released	(8010) [Difficulty Breathing (ALS-786.05)]

PATIENT NARRATIVE:	
Pt was having problem breathing. Givin O2 @15l NRB.	
Review Requested: No	

COMPLAINT	
Chief Complaint Narrative	breathing Difficulty
Complaint Anatomic Location	Chest
Primary Symptom	Breathing Problem
Providers Primary Impression	Respiratory distress

DESTINATION			
Incident Patient Disposition		Treated and Released	

EMS PERSONNEL	ID	ROLE	
(b) (6)	0325	Other	
	0360	Primary Patient Caregiver	

PATIENT #12 - PCR 1080873			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
(b) (6)	(b) (6)	(b) (6)	(b) (6)
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)

PATIENT HISTORY		
Primary Symptom:	What happened to this patient:	Condition Code Number:
Breathing Problem	Treated and Released	(8010) [Difficulty Breathing (ALS-786.05)]

PATIENT NARRATIVE:	
Pt was having problem breathing. Givin O2 @15l NRB.	
Review Requested: No	

COMPLAINT	
Chief Complaint Narrative	Breathing Difficulty
Complaint Anatomic Location	Chest
Primary Symptom	Breathing Problem
Providers Primary Impression	Respiratory distress

DESTINATION	
Incident Patient Disposition	Treated and Released

EMS PERSONNEL	ID	ROLE
(b) (6)	0325	Primary Patient Caregiver
	0360	Secondary Patient Caregiver

PATIENT #13 - PCR 1080912			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Female	()
Race	Ethnicity	DOB	Age
(b) (6)	(b) (6)	(b) (6)	(b) (6)
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)




PATIENT HISTORY		
Primary Symptom:	What happened to this patient:	Condition Code Number:


Pain	Treated and Released	(8018) [Eye Symptoms (non-traumatic) (ALS-379.90)]	
PATIENT NARRATIVE:			
Pt was in close proximity to blast and a window got blown in on her. Pt eye was flushed and object removed.			
Review Requested: No			
COMPLAINT			
Chief Complaint Narrative	Eye was hurting.		
Complaint Anatomic Location	Head		
Primary Symptom	Pain		
Providers Primary Impression	Not Applicable		
EXAM			
<input checked="" type="checkbox"/>	Exam Time:		
	Performed By:		
#	Region	Assessment/Injury	
1	Head - Face	Object in Eye	
DESTINATION			
Incident Patient Disposition		Treated and Released	
EMS PERSONNEL			
	ID	ROLE	
(b) (6)	0325	Primary Patient Caregiver	
	0360	Secondary Patient Caregiver	
PATIENT #14 - PCR 1080919			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
		(b) (6)	
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)
PATIENT HISTORY			
Primary Symptom:	What happened to this patient:	Condition Code Number:	
None	No Treatment Required	(8044) [Trauma, Other (need for monitor or airway) (ALS-518.5)]	
PATIENT NARRATIVE:			
(b) (6) Pt was checked for cuts due to glass blowing in on him. No glass or cuts were found.			
Review Requested: No			
COMPLAINT			
Chief Complaint Narrative	Check up		
Complaint Anatomic Location	Not Applicable		
Primary Symptom	None		
Providers Primary Impression	Not Applicable		
DESTINATION			




Incident Patient Disposition		No Treatment Required	
EMS PERSONNEL	ID	ROLE	
(b) (6)	0325	Primary Patient Caregiver	
	0360	Secondary Patient Caregiver	
PATIENT #15 - PCR 1080927			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
		(b) (6)	
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	
PATIENT HISTORY			
Primary Symptom:	What happened to this patient:	Condition Code Number:	
Bleeding	Treated and Released	(8047) [Trauma, Other (penetrating extremity) (BLS-880.0)]	
PATIENT NARRATIVE:			
Pt stepped on 2 nails. Pt foot was flushed and wrapped.			
Review Requested: No			
COMPLAINT			
Chief Complaint Narrative		stepped on 2 nails	
Complaint Anatomic Location		Extremity-Lower	
Primary Symptom		Bleeding	
Providers Primary Impression		Traumatic injury	
EXAM			
<input checked="" type="checkbox"/>	Exam Time:		
	Performed By:		
#	Region	Assessment/Injury	
1	Foot - Right Anterior	Puncture/stab	
DESTINATION			
Incident Patient Disposition		Treated and Released	
EMS PERSONNEL	ID	ROLE	
(b) (6)	0325	Primary Patient Caregiver	
	0360	Secondary Patient Caregiver	
PATIENT #16 - PCR 1081766			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
		(b) (6)	
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code

5271	BLS, Emergency	kg	0
PATIENT HISTORY			
Primary Symptom:	What happened to this patient:	Condition Code Number:	
Breathing Problem	Treated and Released	(8010) [Difficulty Breathing (ALS-786.05)]	
PATIENT NARRATIVE:			
Pt was having problem breathing. Given O2 @15l NRB.			
Review Requested: No			
COMPLAINT			
Chief Complaint Narrative	Pt was having problem breathing.		
Complaint Anatomic Location	Chest		
Primary Symptom	Breathing Problem		
Providers Primary Impression	Respiratory distress		
DESTINATION			
Incident Patient Disposition		Treated and Released	
EMS PERSONNEL	ID	ROLE	
(b) (6)	0325	Primary Patient Caregiver	
	0360	Secondary Patient Caregiver	
PATIENT #17 - PCR 1081772			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
(b) (6)	(b) (6)	(b) (6)	(b) (6)
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)
PATIENT HISTORY			
Primary Symptom:	What happened to this patient:	Condition Code Number:	
Pain	Treated, Transported by EMS	(8046) [Trauma, Other (fracture/dislocation) (BLS-829.0)]	
PATIENT NARRATIVE:			
Pt stated his back was hurting after he had been knocked back from an explosion. Pt was sitting upright in a chair. Fd units put Pt in a KED and on a back board and transported to CVMC.			
Review Requested: No			
COMPLAINT			
Chief Complaint Narrative	Back pain		
Complaint Anatomic Location	Back		
Primary Symptom	Pain		
Providers Primary Impression	Traumatic injury		

DESTINATION			
Incident Patient Disposition		Treated, Transported by EMS	
EMS PERSONNEL	ID	ROLE	
(b) (6)	0325	Primary Patient Caregiver	
	0360	Driver	
PATIENT #18 - PCR 1081781			
Name	Home Address	Gender	Pregnancy
(b) (6)	(b) (6)	Male	N/A
Race	Ethnicity	DOB	Age
(b) (6)	(b) (6)	(b) (6)	(b) (6)
Unit Number	Unit Service Level	Estimated Body Weight	Pediatric Color Code
5271	BLS, Emergency	(b) (6)	(b) (6)
PATIENT HISTORY			
Primary Symptom:	What happened to this patient:	Condition Code Number:	
Pain	Treated, Transferred Care	(8052) [Burns-Minor (ALS-949.2)]	
PATIENT NARRATIVE:			
Pt was in the house that exploded then moved to house next door. Pt was found on floor with minor burns over most of his body. Pt was given O2 at 15L via NRB mask. Pt was turned over to Mono county medics.			
Review Requested: No			
COMPLAINT			
Chief Complaint Narrative		Burns over body	
Complaint Anatomic Location		Abdomen	
Complaint Organ Agency		Skin	
Primary Symptom		Pain	
Providers Primary Impression		Traumatic injury	
EXAM			
<input checked="" type="checkbox"/>	Exam Time:		
<input checked="" type="checkbox"/>	Performed By:		
#	Region	Assessment/Injury	
	Skin	Burn	
DESTINATION			
Incident Patient Disposition		Treated, Transferred Care	
EMS PERSONNEL	ID	ROLE	
(b) (6)	0325	Primary Patient Caregiver	
	0360	Secondary Patient Caregiver	
INCIDENT IMAGES			
<input checked="" type="checkbox"/> Click to enlarge		<input checked="" type="checkbox"/> Click to enlarge	



 Click to enlarge Click to enlarge Click to enlarge Click to enlarge Click to enlarge Click to enlarge Click to enlarge Click to enlarge


 Click to enlarge

 Click to enlarge Click to enlarge Click to enlarge Click to enlarge


 Click to enlarge

 Click to enlarge


 Click to enlarge Click to enlarge Click to enlarge Click to enlarge


 Click to enlarge


 Click to enlarge Click to enlarge


 Click to enlarge


 Click to enlarge


 Click to enlarge


 Click to enlarge

 Click to enlarge


 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge


 Click to enlarge


 Click to enlarge


 Click to enlarge


 Click to enlarge

 Click to enlarge

 Click to enlarge


 Click to enlarge

 Click to enlarge


 Click to enlarge


 Click to enlarge


 Click to enlarge


 Click to enlarge


 Click to enlarge

 Click to enlarge


 Click to enlarge


 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge


 Click to enlarge


 Click to enlarge


 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge


 Click to enlarge

 Click to enlarge


 Click to enlarge


 Click to enlarge

 Click to enlarge


 Click to enlarge

 Click to enlarge



 Click to enlarge

 Click to enlarge

 Click to enlarge


 Click to enlarge


 Click to enlarge


 Click to enlarge Click to enlarge Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge


 Click to enlarge Click to enlarge

 Click to enlarge

 Click to enlarge Click to enlarge Click to enlarge Click to enlarge Click to enlarge Click to enlarge Click to enlarge


 Click to enlarge


 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge

 Click to enlarge Click to enlarge

A large grid of 40 buttons, arranged in two columns of 20 each. Each button contains a small 'x' icon and the text 'Click to enlarge'. The buttons are arranged in a 20x2 grid, with 10 buttons in each row and 2 buttons in each column. The buttons are arranged in a grid that is 20 rows high and 2 columns wide. Each button is a small rectangle with a thin border. Inside each button, on the left, is a small square containing a black 'x'. To the right of this icon, the text 'Click to enlarge' is written in a small, black, sans-serif font.

Name	Personnel Rank	Apparatus
(b) (6)	Firefighter EMT	Other
(b) (6)	Firefighter EMT	Other
(b) (6)	Firefighter EMT	5230
(b) (6)	Firefighter EMT	5230
(b) (6)	Firefighter EMT	5230
Lightfoot, Michael L	Lieutenant	5220

Preston, Keith A	Captain	Other
Robinson, John E	Fire Inspector	5271
Sullivan, Kevin M	Fire Chief	Other
(b) (6)	Firefighter EMT	5271
	Firefighter EMT	Other

Member Making Report (Fire Chief Kevin M Sullivan): _____

Supervisor (Fire Chief Kevin M Sullivan): _____